

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: BUTTE-SILVER BOW COUNTY

Community No: 300077

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMR	08-08-0674P	09/09/2008	Un-named Zone A Floodplain - Near the Continental Drive/Irene Street intersection	3000770183D	30093C0326E

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	99-08-107A	01/21/1999	PORTION OF SECTION 18, T1S, R9W, P.M.M. (CERTIFICATE OF SURVEY 390-B, TRACT B)	3000770340D	30093C0575E
LOMA	00-08-291A	08/28/2000	3500 QUINCY STREET -- PORTION OF SECTION 28, T3N, R8W, M.P.M.	3000770191D	30093C0326E
LOMA	00-08-347A	11/01/2000	EAST BLACK TAIL PLACER, PORTIONS OF SECTIONS 15, 22, & 23, T2N, R7W, M.P.M.	3000770285D	30093C0340E
LOMA	03-08-0271A	04/16/2003	871 PUMP HOUSE ROAD -- VALENTINE PLACER MINERAL SURVEY NO. 6153, TRACT C, PORTION OF SECTION 12, T1	3000770340D	30093C0425E
LOMA	04-08-0327A	03/12/2004	NORTHERN PACIFIC ADDITION, BLOCK 32, LOTS 13-14 -- 2004 HANCOCK AVENUE	3000770183D	30093C0326E
LOMA	05-08-0104A	01/05/2005	627 SOUTH RIVER ROAD -- PORTION OF SECTION 19, T1S, R9W, M.P.M.	3000770340D	30093C0575E
LOMA	05-08-0661A	09/16/2005	357 CONNOR LANE - COS NO. 754-B, TRACT A	3000770420D	30093C0590E
LOMA	06-08-0130A	12/29/2005	PORTION SECTION 19, T1S, R9W, M.P.M. -- 731 SOUTH RIVER ROAD	3000770340D	30093C0575E

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: BUTTE-SILVER BOW COUNTY

Community No: 300077

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	06-08-B304A	05/10/2006	KECK ACRES MINOR SUBDIV, LOT 5 -- 219 KELSEY LANE	3000770193D	30093C0328E
LOMA	07-08-0210A	01/16/2007	TRACT B-1, C.O.S. No. 390-B -- 195 SOUTH RIVER ROAD	3000770340D	30093C0575E
LOMR-FW	08-08-0061A	01/22/2008	HURLBURT ADDITION, BLOCK 11, LOT 1 -- 1834 YALE STREET	3000770191D	30093C0307E
LOMA	08-08-0349A	04/15/2008	MERIWETHER RANCH PUD, LOTS 2 & 5 -- 440 & 570 COTTON WILLOW ROAD	3000770420D	30093C0590E
LOMA	08-08-0638A	07/10/2008	MERIWETHER RANCH PUD, LOTS 2 & 5 -- 440 & 570 COTTON WILLOW ROAD	3000770420D	30093C0590E
LOMA	09-08-0051X	11/20/2008	MERIWETHER RANCH PUD, LOTS 2 & 5 -- 440 & 570 COTTON WILLOW ROAD	3000770420D	30093C0590E
LOMA	10-08-0326A	03/11/2010	(65-FW) TRACK 18D, MCGUINNESS TRACTS -- 126 PAINTED MEADOW	3000770193D	30093C0328E

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
LOMA	199530086MBJ	12/11/1980	PORTION OF SECTION 18, T1S, R9W	1
102	199210618MBJ	07/23/1987		1
102	01-08-017P	03/01/2001	WAL-MART EXPANSION STORE	4
LOMA	03-08-0297A	04/16/2003	SILVER BOW OAKS L.L.C. MINOR SUBDIV, TRACT 1B -- 3939 HARRISON AVENUE	4

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: BUTTE-SILVER BOW COUNTY

Community No: 300077

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		